

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4N. R. 14E.

CORNER CODE INDEX

11M A TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B			6				5					4				3				2				1		B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE V3(2)

L1602

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1836 (JUNE) BURNHAM WEST RANDOM BETWN. SECS 30 & 31
4620 DRY PRAIRIE
5074.08 INT. RANGE LINE 57.42' WEST WD 14 S50E
304.92'; WD 18 N78E 300.96' FIRST RATE BUR
OAK OPENINGS & DRY PRAIRIE.
EAST CORRECTED BETWN. SECS 31 & 30 NO STATIONS
2434.08 SET ¼ SEC POST BUR O N38W 23.1' BUR OAK
10 N61E 28.38'
4269.54 BUR OAK 9 IN. DIA
5074.08 TO CORNERS
- 1871 RUBER VOL 2 PG 80 COR LOST. ESTABLISHED IT FROM SEC
COR DROVE STAKE & PUT HH STONE ON E & W SIDES. 2437.96'
VAR 4-35 TO SW COR SEC 30, 2644.12 VAR 4-35 TO SE COR
SEC 30. USED TO SUBDIVIDE SEC 30. 2427.26' FROM W ¼
COR TO CENTER OF SEC 30.
- 1884 RUBER VOL 2 PG 377 FD STAKE & STONE SET BY SELF. SET
IN PLACE OF STAKE SANDSTONE 12X12X6 PUT HH ON N & S
SIDES. USED TO SUBDIVIDE SEC 31. 2471.7 FROM W ¼ COR
TO CENTER OF SEC 31, 2647.10 FROM E ¼ COR SEC 31 TO
CENTER OF SEC 31, 2638.02 FROM S ¼ COR SEC 31 TO
CENTER OF SEC 31.
- 1962 BATTERMAN VOL 4 PG 138 CUT CROSS AT OR NEAR THE N ¼
COR SEC 31 4-14 AT SINGLE PROPORTIONAL MEASUREMENT &
USING THE CENTER OF STH 59 FOR LINE. SET TIES. ALL
BEARINGS ARE TRUE BEARING SEE PG 123. NORTH LINE OF NW
¼ SEC 31 IS N89-46-35W AND N33-36E 43.18 TO NE
REFERENCE PIPE.
- 1980 BARNES VOL 6 PG 41 SHOWS RUBER & ORIG RECORD
DISTANCES.
- 1982 BARNES V-3 LIMA FIELD BK 1 PG 60 SET PK FROM TIES.
COR. MONUMENT WILL BE DESTROYED NEXT YEAR IN A ROAD
CONSTRUCTION PROJECT. 283,348.39; 2,298,796.50 ELEV.
975'. FD CUT CROSS IN TOP OF BRIDGE WING WALL, NE
(43.18) & SE (48.40) REFERENCE PIPES. SET PK FROM
REFERENCE TIES. PK @ CENTER OF PVMT.
- 1982 LIMA TWP PROJECT FIELD NOTES. TIED IN PK FROM WIDOT
STA 253+84 (A FD PK/FLASHER)
- 1983 WIDOT STH59 R/W PLANS PROJECT #3143-00-21 SHEET 4.B
PK NAIL 283,349.34; 2,298,795.97 O.15' PERPENDICULAR TO
REF LINE AT STA 200+73.02 S0-26-42E
- 1985 WIDOT V-3(1) SET TIES FOR WHAT APPEARS TO BE SEC COR.
220+73.0 O.15' PERPENDICULAR TO REF LINE (RT)

IN SEP 2001 FD DOT'S REFERENCE PINS ON SOUTH SIDE, THE NE
1" REFERENCE PIPE, & TWO PK'S AT THE CORNER LOCATION. IN
APRIL 2002 USED RECORD TIE TO NE REFERENCE PIPE AND
RECORD ANGLE ALONG SW ¼ SECTION LINE TO THE NE
REFERENCE PIPE TO ESTABLISH THE COR. LOCATION. SET STEEL
SURVEY SPIKE WITH THE FOLLOWING CAPTION STAMPED ON TOP
"SURVEY MARK"

THE OLD SE REF. TIE WAS PROBABLY DESTROYED BY
UNDERGROUND UTILITY. OLD BRIDGE WAS REPLACED WITH CMP.
THE TWO FD PK'S WERE PROBABLY SET BY USING RECORD
DISTANCES TO ONLY TWO WIDOT TIES & NOT THE SAME TIES.

SHEET 2/OF 3

V-3(2)

May 15 2002
Donald Barnes

LI602

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED OBLITERATED EVIDENCE LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

COMPUTED POSITION FOR WIDOT STA 220+73.02 CHECKS WITH WIDOT NW & NW TIE. WIDOT SOUTH TIE DOES NOT CHECK WITH RECORD DISTANCE. TIES ON BRIDGE AND SE REFERENCE PIPE ARE GONE. USED RECORD DISTANCE TO NE REFERENCE PIPE AND RECORD ANGLE AS SHOWN IN SKETCH. APPEARS WIDOT RECORD DISTANCES TO STA 220+73.02 WAS USED TO SET PK NAILS.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

SHEET 2 OF 3

Donald Barnes
5/15/02

CORNER CODE **V-3(1)**
A.E. 7.08 REQUIREMENT

