

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N., R. 10 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6													3											1
D																									
E																									
F																									
G	7													10											12
H																									
I																									
J																									
K																									
L	18													15											13
M																									
N																									
O																									
P	19													22											24
Q																									
R																									
S	30													27											25
T																									
U																									
V																									
W																									
X	31													34											36
Y																									
Z																									

UNION TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____


Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

 CORNER MONUMENT  WITNESS MONUMENT

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____ SHEET _____ OF _____

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE P 13 (1)

UN577

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1857 CHURCH VOL 1 PG 70 USED CORNER FOR SUBDIVIDING SECTION 2 BUT STATES NOTHING ABOUT THE CORNER.
- 1870 RUGER REMONUMENTATION PG 96 NORTH ON EAST LINE OF SE 1/4 SEC 21 ON A VAR 7-00 OFFSET EAST 6.93' AT 2665.74 INTERSECTED 1/4 LINE 6.6' WEST OF 1/4 COR FD BOTH BEARING STUMPS & ESTABLISHED 1/4 COR FROM THEM. CORRECTED VAR 6-43
NORTH ON EAST LINE OF NE 1/4 SEC 21 ON A VAR 7-00 AT 2658.64 INTERSECTED NORTH BOUNDARY LINE 1.98' EAST OF COR.
CORRECTED VAR 7-02
- 1893 BLEEDORN VOL 2 PG 431 USED CORNER TO SUBDIVIDE SECTION 21 DOESN'T STATE THE TYPE OF MONUMENT FOUND MON. 2666.4 TO SE COR SEC 21.
- 1899 BROWN VOL 2 PG 512 DOESN'T STATE THE TYPE OF MONUMENT FOUND. CALLS FOR 2657.49 TO THE CENTER OF SECTION 21 AND 5326.53 TO THE W 1/4 COR SEC 21.
- 1966 FRUDDEN PLAT OF SURVEY USED THE CORNER BUT STATES NOTHING ABOUT IT. CALLS FOR 2617.00 TO THE CENTER OF SECTION 22 AND 71.30 PROPERTY CORNER ALONG THE RAILROAD R/W.
- 1972 THOUSAND GSM 3 PG 4 PLACED AN IRON PIPE.
- 1977 TALARCZYK GSM VOL 7 PG 10 FOUND 1 PIPE.
- 1982 COMBS PLAT OF SURVEY USED CORNER TO SUBDIVIDE SECTION 22. LEGEND CALLS FOR IRON PIN.
- 1990 BARNES P-13 FOUND A 1/2 PIN & A 1 1/4 PIN. FOUND SEVERAL PIECES OF THE TOP OF THE CUT LIMESTONE ON TOP OF GROUND ABOUT A 15 TO THE NW OF THE 1 1/4" PIN. FOUND SEVERAL PIECES OF THE CUT LIMESTONE 15 DEEP AT AND WEST OF THE 1/2 PIN. DUG AND FOUND BOTTOM OF THE CUT LIMESTONE. 0.88' NORTH OF THE 1/2 PIN. PLACED POLY MONUMENT ON TOP OF STONE & GARSONITE ON NORTH SIDE. ACCEPTED FOUND CUT LIMESTONE. REFERENCED CUT LIMESTONE. 2672.10 TO SE COR SEC 21 & 2664.00 TO NE COR SEC 21 WITH COR BEING 0.79' WEST OF A STRAIGHT LINE BETWEEN THE NE & SE CORNERS OF SEC 21.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED CORNER OF RECORD.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Donald Barnes
05/02/00
Emboss

Number of included sheets 1

CORNER CODE P-13(1)

A-E 7.08 REQUIREMENT