

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 3 N., R. 11 E

### CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	7																								
H																									
I																									
J																									
K	8																								
L																									
M																									
N																									
O																									
P	19																								
Q																									
R																									
S																									
T	30																								
U																									
V																									
W																									
X	31																								
Y																									
Z																									

CENTER TWP

ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE L-3

cel554

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1863 LOCKE VOL 1 PG 181 SET LIMESTONE 12X10X6. CALLS FOR 2656.5 TO E 1/4 COR SEC 18, 2653.2 TO N & S 1/4 CORNERS OF SEC 18, & 2537.37 TO W 1/4 COR SEC 18. APPEARS THAT HE FOLLOWED THE GENERAL LAWS OF WISCONSIN, 1862 CHAPTER 120. ACCORDING TO THAT LAW THE CENTER OF SECTION WAS NOT ESTABLISHED BY THE INTERSECTION OF THE 1/4 LINES.

DUG LARGER 4' DEEP HOLE AS SHOWN AND FOUND NOTHING. FOUND A VERY LIMITED AMOUNT OF BARB WIRE. AREA WAS PROBABLY PREVIOUSLY CLEARED.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?  
DID NOT ESTABLISH CORNER.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under by direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

*Donald Barnes*  
OCT 3, 1996  
emboss

Number of included sheets \_\_\_\_\_

CORNER CODE

A-E 7.08 REQUIREMENT

43



9661k 20  
*Donald Barnes*

N 1/4  
 COR

NW COR

FD ALUM

N89-32-41E 2564.28  
 RUGER 1876 2562.12  
 1226.94 RUGER 1876 VAR 6-18 1335.18  
 HARRISON 1833 2532.42

N89-32-41E 2650.16  
 RUGER 1876 2647.92  
 1323.96 RUGER 1876 VAR 6-24 1323.96  
 LOCKE 1864 2643.96  
 HARRISON 1833 2640

NE COR

FD ALUM

BARNES 1977 2664.23  
 LOCKE 1863 2653.86  
 S0-15-38E 2664.22

604.56 604.56 LOCKE 1328.25  
 LOCKE 1863 2537.37  
 FENCE N89-29E 2543.9

FENCE S0-11W 2661.6  
 LOCKE 1863 2653.2

SEC 18

LOCKE 1864 1323.96  
 LOCKE 1863 2656.5

HARRISON 1833 2640  
 LOCKE 1863 2655.18  
 LOCKE 1863 VAR 7-30  
 BARNES 1979 2657.45  
 N0-07-52W 2657.54

W 1/4 COR  
 FD ALUM

BARNES 1977 2663.30  
 LOCKE 1863 2653.86  
 S0-16-13E 2663.36

1326.93 LOCKE 1326.93

FARM FIELD  
 NO FENCE LINE

1326.6 LOCKE 1326.6  
 LOCKE 2653.2  
 FENCE S0-13E 2659.9

1334 BARNES 79 1328.1

1326.27 LOCKE 1864 1326.27  
 1332 BARNES 1976 1332

FD ALUM

E 1/4 COR

HARRISON 1833 2640  
 LOCKE 1863 2655.18  
 LOCKE 1864 2651.88  
 LOCKE 1863 VAR 7-30  
 S0-07-40E 2657.44

FD C.I.

SW COR

HARRISON 1833 2521.86  
 604.56 604.56 LOCKE 1327.92  
 1209.12 LOCKE 1863 1327.92  
 LOCKE 1863 VAR 7-50  
 LOCKE 1863 2537.04  
 S89-24-20W 2541.44

HARRISON 1833 2640  
 LOCKE 1864 2652.54  
 LOCKE 1863 2655.84  
 LOCKE 1863 VAR 7-50  
 S89-24-20W 2660.45

FD ALUM

SE COR