



1866 LOCKE REMONUMENTATION INTERSECTED NORTH BOUNDARY 4 LINKS WEST OF CORNER. FOUND OLD STAKE IN CENTER OF HIGHWAYS AND NEARLY IN LINE WITH FENCE RUNNING NORTH. PLACED CUT LIMESTONE. SHOWS A DISTANCE OF 2654.86 TO THE NORTH QUARTER CORNER OF SECTION 3, 2657.49' TO THE NORTH QUARTER CORNER OF SECTION 2, AND 2702.70 TO THE EAST QUARTER CORNER OF SECTION 3.

1877 RUGER VOL 2 PG 234 FOUND STONE MONUMENT. USED CORNER TO SUBDIVIDE THE NW QUARTER OF SECTION 2. SHOWS A DISTANCE OF 2654.19 TO THE NORTH QUARTER CORNER OF SECTION 2.

1933 SUNNY VOL 3 PG 235 SET 1" X 36" PIPE IN CONCRETE PAVEMENT 7.9' NORTH OF CENTERLINE OF PAVEMENT. SHOWS A DISTANCE OF 2653.6 TO THE NORTH QUARTER CORNER OF SECTION 3 AND 2656.9 TO THE NORTH QUARTER CORNER OF SECTION 2

1958 BATTERMAN JR. VOL 3 PG 235 FOUND 1" PIPE 1' FROM NORTH EDGE OF PAVEMENT.

1977 BARNES VOL 5 PG 364 FOUND 1" PIPE 0.3' DEEP AND REPLACED WITH ALUMINUM MONUMENT. PLACED REFERENCE PIPES. FOUND LARGE 6 1/2" X 9 1/2" X 12' STONE POINT UP AND UNDER THAT FOUND CUT LIMESTONE. CUT LIMESTONE IS 2.6' DEEP. PLACED MAGNET ON TOP OF STONE. EXCAVATION INDICATES THAT SUNNY DID NOT DIG FOR CORNER.

(c) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.

ACCEPTED FOUND CUT LIMESTONE.

(d) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

